

CONDITION CHECK REPORT

BF No.	BH589764	CHASSIS No.	SCP100-0081981
--------	-----------------	-------------	-----------------------

DATE 2020 / 11 /

1	TIMING BELT CHANGE		YES					KM	13	POWER WINDOW (R FRONT)	<input checked="" type="checkbox"/>	NG			NONE	
2	COOLANT LEVEL	<input checked="" type="checkbox"/>	NG	LEAK					14	POWER WINDOW (L FRONT)	<input checked="" type="checkbox"/>	NG			NONE	
3	ENGINE OIL LEVEL	<input checked="" type="checkbox"/>	NG	DIRT					15	POWER WINDOW (R REAR)	<input checked="" type="checkbox"/>	NG			NONE	
4	OIL LEAKING	<input checked="" type="checkbox"/>	NG	SMALL	BIG				16	POWER WINDOW (L REAR)	<input checked="" type="checkbox"/>	NG			NONE	
5	TIRE (R FRONT)	<input checked="" type="checkbox"/>	NG	125/60 R 16		RFT			17	A/C CONDITION	<input checked="" type="checkbox"/>	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	<input checked="" type="checkbox"/>	NG	175/60 R 16		RFT			18	INTERIOR CONDITION	<input checked="" type="checkbox"/>	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	<input checked="" type="checkbox"/>	NG	175/60 R 16		RFT			19	CHECK / WARNING LAMP	<input checked="" type="checkbox"/>	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	<input checked="" type="checkbox"/>	NG	175/60 R 16		RFT			(COMMENT) 7月14日23日						TESTER CHECK	
9	ENGINE NOISE	<input checked="" type="checkbox"/>	NG	E/G	OTHERS											
10	ENGINE CONDITION	<input checked="" type="checkbox"/>	NG	IDLING	SMOKE											
11	EXHAUST LEAK	<input checked="" type="checkbox"/>	NG	MUFFLER RUSTY	MISSING PARTS											
12	TRANSMISSION (AT / MT)	<input checked="" type="checkbox"/>	NG	SHOCK	NOISE	SLIP										
OPTION																
<input checked="" type="checkbox"/> RADIO		<input checked="" type="checkbox"/> CD		<input checked="" type="checkbox"/> DVD		<input type="checkbox"/> SUN ROOF		<input type="checkbox"/> FLIP DOWN MONITOR								
<input type="checkbox"/> REAR MONITOR		<input type="checkbox"/> BACK CAMERA		<input type="checkbox"/> CRUISE CONTROL		<input type="checkbox"/> POWER SLIDING DOOR (LEFT)		<input type="checkbox"/> POWER SLIDING DOOR (RIGHT)								
<input type="checkbox"/> POWER BACK DOOR																
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。										(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ（マーカで囲んで）、その他目立つ破損部分があった場合は、写真撮影をお願いします。						

YARD	ナガセ自動車株式会社
------	------------

INSPECTER	花原
-----------	----

AA SHEET
