

CONDITION CHECK REPORT

BF No.	BH594400	CHASSIS No.	LA300S-1026982
--------	----------	-------------	----------------

DATE 2020 / 11 / 18

No.	Item	Status	Remarks	Type	No.	Item	Status	Remarks	Type	No.	Item	Status	Remarks	Type	
1	TIMING BELT CHANGE			KM	13	POWER WINDOW (R FRONT)	OK		NG				NONE		
2	COOLANT LEVEL	OK			14	POWER WINDOW (L FRONT)	OK		NG				NONE		
3	ENGINE OIL LEVEL	OK			15	POWER WINDOW (R REAR)	OK		NG				NONE		
4	OIL LEAKING	OK			16	POWER WINDOW (L REAR)	OK		NG				NONE		
5	TIRE (R FRONT)	OK	155/65R/14	RFT	17	A/C CONDITION	OK		NG		WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	155/65R/14	RFT	18	INTERIOR CONDITION	X	NG			DIRT	SMOKING SMELL	OTHER SMELL		
7	TIRE (R REAR)	OK	155/65R/14	RFT	19	CHECK / WARNING LAMP	OK		E/G		ABS	AIRBAG	OTHER		
8	TIRE (L REAR)	OK	155/65R/14	RFT	(COMMENT) スパ3の付ス車 ミートハタリ、シミ、ヨレ小								TESTER CHECK		
9	ENGINE NOISE	OK	E/G	OTHERS											
10	ENGINE CONDITION	OK	IDLING	SMOKE											
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS											
12	TRANSMISSION (AT/MT)	OK	SHOCK	NOISE									SLIP		
OPTION															
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR											
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)											
POWER BACK DOOR															

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。
 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ（マーカ-で囲んで）、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	ナガセ自動車株式会社
------	------------

INSPECTER	尾崎 竜也
-----------	-------

AA SHEET
