

SPECS

| | | | |
|-------------------|-------------|------------------|----------------------|
| Ref No | BH601034 | Location Country | Thailand |
| Chassis # | CHASSIS6988 | Ver/Class | 2.7 |
| Model Code | - | Ext.Color | Gray |
| Engine Size | 2,700 cc | Fuel | Petrol |
| Drive | 4WD | Seats | 7 (7) |
| Transmission | Automatic | Doors | 5 |
| Mileage | 309,535 km | Weight | 2,000 kg |
| Engine Code | - | Dimension | 4.65 × 1.76 × 1.87 m |
| Steering | Right | M3 | 15.304 |
| Registration Year | 2006 | | |
| Manufacture Year | 2006 | | |

STANDARD FEATURES

| | | | | | | | |
|----------------|---|-----------------|---|-------------------|---|--------------|---|
| CD Player | | Sun Roof | | Leather Seat | ✓ | Alloy Wheels | ✓ |
| Power Steering | | Power Window | ✓ | A/C | ✓ | ABS | |
| Airbag | | Radio | ✓ | CD Changer | | DVD | |
| TV | | Power Seat | | Back Tire | | Grill Guard | |
| Rear Spoiler | | Central Locking | | Jack | ✓ | Spare Tire | ✓ |
| Wheel Spanner | ✓ | Fog Lights | | Back Camera | | Push Start | |
| Keyless Entry | | ESC | | 360 Degree Camera | | | |
| | | | | | | | |

SUPPLIER'S CONDITION REPORT

| | | | |
|-------------------|---------|-----|------|
| Corrosion | NO | YES | |
| Under Body Holes | NO | YES | |
| Under Body Broken | NO | YES | |
| Engine | Working | NG | |
| Brake System | Working | NG | |
| Heater | Working | NG | |
| Power Window | Working | NG | |
| Transmission | Working | NG | |
| A/C | Working | NG | |
| Audio System | Working | NG | |
| 4WD | Working | NG | NONE |

COMMENTS

DATE 2020/11/17