

Forester

CONDITION CHECK REPORT

BH No.	607095	CHASSIS No.	SG5-089559	DATE	20/11/21
--------	--------	-------------	------------	------	----------

1	TIMING BELT CHANGE	(NO)	YES			13	POWER WINDOW (R FRONT)	(OK)	NG			NONE		
2	COOLANT LEVEL	(OK)	NG	LEAK	7/11	14	POWER WINDOW (L FRONT)	(OK)	NG			NONE		
3	ENGINE OIL LEVEL	(OK)	NG	DIRT	(1.0L)	15	POWER WINDOW (R REAR)	(OK)	NG			NONE		
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	(OK)	NG			NONE		
5	TIRE (R FRONT)	(OK)	NG	215/55R17	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	(OK)	NG	215/55R17	RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT	SMOKING SMELL	OTHER SMELL		
7	TIRE (R REAR)	(OK)	NG	215/55R17	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER		
8	TIRE (L REAR)	(OK)	NG	215/55R17	RFT	(COMMENT) 全体的にや (OK)						TESTER CHECK		
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS									
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE									
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT/MT)	(OK)	NG	SHOCK	NOISE							SLIP		
OPTION														
(RADIO)		(CD)		DVD		SUN ROOF		FLIP DOWN MONITOR						
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)						
POWER BACK DOOR														
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」で記載します。														
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オーグメントシートをチェックして、10-83以上の固みキズ、フロントガラスの割れやヒビ(マーカで隠して)、その他目立つ破損部分があった場合は、写真撮影をお願いします。														

YARD	野田	INSPECTER	K.S	AA SHEET	0
------	----	-----------	-----	----------	---