

CONDITION CHECK REPORT

BH No.	608970	CHASSIS No.	RK1-1003014
--------	--------	-------------	-------------

DATE 2020 / 12 / 1

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE					
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE					
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE					
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE					
5	TIRE (R FRONT)	OK	NG	205/55 R16		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C	NONE					
6	TIRE (L FRONT)	OK	NG	/	R	RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL						
7	TIRE (R REAR)	OK	NG	/	R	RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER						
8	TIRE (L REAR)	OK	NG	/	R	RFT	<div style="border: 1px solid black; padding: 5px;">(COMMENT)</div> <div style="font-size: 1.5em; margin-top: 20px; text-align: center;"> 4 SIL = 2 (小) </div> <div style="font-size: 1.5em; margin-top: 10px; text-align: center;"> 78 ワイヤ - みえ </div> <div style="font-size: 1.5em; margin-top: 10px; text-align: center;"> 3rd エント 根 </div> <div style="font-size: 1.5em; margin-top: 10px; text-align: right;"> 60P23 根 </div>					TESTER CHECK						
9	ENGINE NOISE	OK	NG	E/G	OTHERS													
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE													
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS													
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP												
OPTION																		
	RADIO	9	9D	9	SUN ROOF	FLIP DOWN MONITOR												
	REAR MONITOR	9	9	9	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)												
	POWER BACK DOOR																	
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。																		

YARD ECL木更津

INSPECTER カサハシ

AA SHEET 9