

# CONDITION CHECK REPORT

BH No.	608985	CHASSIS No.	RD5-1008406
--------	--------	-------------	-------------

DATE 2020/11/26

1	TIMING BELT CHANGE	YES	NG	LEAK	DIRT	SMALL	BIG	13	POWER WINDOW (R FRONT)	OK	NG	NONE
2	COOLANT LEVEL	OK	NG					14	POWER WINDOW (L FRONT)	OK	NG	NONE
3	ENGINE OIL LEVEL	OK	NG					15	POWER WINDOW (R REAR)	OK	NG	NONE
4	OIL LEAKING	OK	NG					16	POWER WINDOW (L REAR)	OK	NG	NONE
5	TIRE (R FRONT)	OK	NG	205/70 R15	RFT			17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE
6	TIRE (L FRONT)	OK	NG	/ R	RFT			18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	/ R	RFT			19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	↓ R	RFT			(COMMENT)  <div style="font-size: 2em; font-family: cursive;">42D</div> <div style="font-size: 2em; font-family: cursive;">75327°</div>				TESTER CHECK
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP						
OPTION												
RADIO	C D X	DVD	SUN ROOF	FLIP DOWN MONITOR								
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR												
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願いします。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オーケションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マークで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD	ECL木更津
------	--------

INSPECTER	カサハラ
-----------	------

AA SHEET	9
----------	---