

CONDITION CHECK REPORT

BH NO.	612068	CHASSIS No.	WBAVR72050 KW39428
--------	--------	-------------	--------------------

DATE 2020/11/27

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE		
2	COOLANT LEVEL	OK	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE		
3	ENGINE OIL LEVEL	OK	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE		
4	OIL LEAKING	OK	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE		
5	TIRE (R FRONT)	OK	205/55R/6		RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	/	R	RFT	(COMMENT) シヤッキ. 修理キット 欠 (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						
9	ENGINE NOISE	OK	E/G	OTHERS								
10	ENGINE CONDITION	OK	IDLING	SMOKE								
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	SHOCK	NOISE	SLIP							
OPTION												
RADIO		C D		DVD		SUN ROOF		FLIP DOWN MONITOR				
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)				
POWER BACK DOOR												

TESTER CHECK

YARD	カナリア 伊勢湾海運
------	------------

INSPECTOR	宇 庄
-----------	-----

AA SHEET	✓
----------	---