

## CONDITION CHECK REPORT

BF No.	<b>BH610118</b>	CHASSIS No.	<b>BF22-104253</b>
--------	-----------------	-------------	--------------------

DATE 2020 / 11 / 25

1	TIMING BELT CHANGE		YES			KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG	LEAK			14	POWER WINDOW (L FRONT)	OK	NG				NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15	POWER WINDOW (R REAR)	OK	NG				NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	OK	NG				NONE
5	TIRE (R FRONT)	OK	NG	175-1	R 1X	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	175-1	R 1X	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	175-1	R 1X	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	175-1	R 1X	RFT	(COMMENT)  ○ E/G 不作動 不作動 不作動 ○ A/C 交換済み ○ 天張たぶみ ○ 車内全体汚れ ○ シート・ドア内張破れ <span style="font-size: 1.5em;">✕</span> 高さ 211cm					TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP								
OPTION														
RADIO		C D		DVD		SUN ROOF		FLIP DOWN MONITOR						
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)						
POWER BACK DOOR														
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。														

YARD	ナガセ自動車株式会社
------	------------

INSPECTER	栗岡
-----------	----

AA SHEET
----------