

CONDITION CHECK REPORT

BH No.	616 059	CHASSIS No.	H77W-5502423
--------	---------	-------------	--------------

DATE 2020/11/27

1	TIMING BELT CHANGE		YES		13	POWER WINDOW (R FRONT)		OK	NG		NONE		
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG		NONE			
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG		NONE			
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE			
5	TIRE (R FRONT)	OK	X NG	215/70R16		RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	X NG	1	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	X NG	1	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	X NG	1	R	RFT	<div style="font-size: 1.5em; font-family: cursive; margin-bottom: 10px;"> 車検 合格 2944円 済 済 </div> <p>(COMMENT)</p> <p>TESTER CHECK</p>						
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
RADIO		BACK CAMERA		SUN ROOF		FLIP DOWN MONITOR							
REAR MONITOR		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)							
POWER BACK DOOR													
<p>(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」をお願いします。</p> <p>(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オーゲメントシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。</p>													

YARD	ECL木更津
------	--------

INSPECTER	[Signature]
-----------	-------------

AA SHEET	9
----------	---