

# CONDITION CHECK REPORT

3 Series

BF No.	6222100	CHASSIS No.	WBAVR72020 KN37572	DATE	20 / 11 / 29
--------	---------	-------------	--------------------	------	--------------

1	TIMING BELT CHANGE	<input checked="" type="radio"/> No	YES	KM			13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG	NONE								
		<input type="radio"/> OK	NG	LEAK					14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG	NONE						
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT			15	POWER WINDOW (R REAR)	<input checked="" type="radio"/> OK	NG	NONE								
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG		16	POWER WINDOW (L REAR)	<input checked="" type="radio"/> OK	NG	NONE								
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	255 / 45 R 17		RFT	17	A/C CONDITION	<input checked="" type="radio"/> OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE						
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	255 / 45 R 17		RFT	18	INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	DIRT	SMOKING SMELL	OTHER SMELL						
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	255 / 40 R 17		RFT	19	CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER						
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	255 / 40 R 17		RFT	(COMMENT)				TESTER CHECK								
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS														
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE														
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS														
12	TRANSMISSION (AT / MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE	SLIP													
OPTION																			
<input checked="" type="radio"/> RADIO	<input checked="" type="radio"/> CD	DVD	SUN ROOF	FLIP DOWN MONITOR															
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)															
POWER BACK DOOR																			

(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	USS 口シ 野子田	INSPECTER	KS	AA SHEET	0
------	------------	-----------	----	----------	---