

CONDITION CHECK REPORT

No.	BH637356	CHASSIS No.	FB511B-403377	DATE	2020 / 12 / 05
-----	----------	-------------	---------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG				NONE					
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG	LEAK			14 POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG				NONE					
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE					
4	OIL LEAKING	OK	<input checked="" type="radio"/> NG	<input checked="" type="radio"/> SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE					
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	6.50 / 0	R 15	RFT	17 A/C CONDITION	OK	<input checked="" type="radio"/> NG	WIND BLOWS OK	<input checked="" type="radio"/> CAN'T OPERATE	A/C NONE						
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	6.50 / 0	R 15	RFT	18 INTERIOR CONDITION	OK	<input checked="" type="radio"/> NG	<input checked="" type="radio"/> DIRT	SMOKING SMELL	OTHER SMELL						
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	165 / 0	R 13	RFT	19 CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER						
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	165 / 0	R 13	RFT	(COMMENT) OIL LEAKING: NG : SMALL AC: NG : CANNOT OPERATE INTERIOR: NG : DIRT エンジンヘッドオイルにじみ エアコンスイッチ欠 天張り汚れキズ ハンドルカバー シフトノブスレ大 ドア内張りハゲ 室内汚れキズ シート破れ焦げ穴スレへたり 飛び石					TESTER CHECK						
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS													
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE													
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS													
12	TRANSMISSION (AT / <input checked="" type="radio"/> MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE	SLIP												
OPTION																		
<input checked="" type="radio"/> RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR														
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)														
POWER BACK DOOR																		
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。											

YARD	藤原A C第3
------	---------

INSPECTER	nyokai
-----------	--------

AA SHEET	<input checked="" type="radio"/>
----------	----------------------------------