

CONDITION CHECK REPORT

BH No.	655/38	CHASSIS No.	Z21A - 0405125
--------	--------	-------------	----------------

DATE **20.20 / 12 / 18**

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE			
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE			
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE			
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE			
5	TIRE (R FRONT)	OK	NG	175/65 R14		RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE		
6	TIRE (L FRONT)	OK	NG	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL		
7	TIRE (R REAR)	OK	NG	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER		
8	TIRE (L REAR)	OK	NG	/	R	RFT	<div style="border: 1px solid black; padding: 5px;"> <p style="margin: 0;">(COMMENT)</p> <p style="font-size: 1.5em; margin: 5px 0;">中々OK</p> <p style="font-size: 1.5em; margin: 5px 0;">三ヶ所</p> </div>						TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS										
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE										
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS										
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP									
OPTION															
RADIO	CD	DVD		SUN ROOF		FLIP DOWN MONITOR									
REAR MONITOR	BACK CAMERA	CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)									
POWER BACK DOOR															
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。								

YARD	ECL木更津
------	--------

INSPECTER	林
-----------	---

AA SHEET	9
----------	---