

CONDITION CHECK REPORT

1517 F-7-

BH No.	656454	CHASSIS No.	FE537B520023
--------	--------	-------------	--------------

DATE 2020/12/15

No.	Item	YES	NG	Leak/Other	RFT	KM	Item	OK	NG	E/G	ABS	AIRBAG	OTHER					
1	TIMING BELT CHANGE						13 POWER WINDOW (R FRONT)	<input checked="" type="checkbox"/>					NONE					
2	COOLANT LEVEL	<input checked="" type="checkbox"/>		LEAK			14 POWER WINDOW (L FRONT)	<input checked="" type="checkbox"/>					NONE					
3	ENGINE OIL LEVEL	<input checked="" type="checkbox"/>		DIRT			15 POWER WINDOW (R REAR)	<input checked="" type="checkbox"/>					NONE					
4	OIL LEAKING	<input checked="" type="checkbox"/>		SMALL	BIG		16 POWER WINDOW (L REAR)	<input checked="" type="checkbox"/>					NONE					
5	TIRE (R FRONT)	<input checked="" type="checkbox"/>		6.50' - R 16	RFT		17 A/C CONDITION	<input checked="" type="checkbox"/>			WIND BLOWS OK	CAN'T OPERATE	A/C NONE					
6	TIRE (L FRONT)	<input checked="" type="checkbox"/>		6.50' - R 16	RFT		18 INTERIOR CONDITION	<input checked="" type="checkbox"/>			DIRT	SMOKING SMELL	OTHER SMELL					
7	TIRE (R REAR)	<input checked="" type="checkbox"/>		6.50' - R 16	RFT		19 CHECK / WARNING LAMP	<input checked="" type="checkbox"/>		E/G								
8	TIRE (L REAR)	<input checked="" type="checkbox"/>		6.50' - R 16	RFT		(COMMENT) 72-4WPC 3ヶ所 バッテリー - エコー (85D 26R x 2) 交換要ス 格納ミテ不良											
9	ENGINE NOISE	<input checked="" type="checkbox"/>		E/G	OTHERS								TESTER CHECK					
10	ENGINE CONDITION	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	IDLING	SMOKE													
11	EXHAUST LEAK	<input checked="" type="checkbox"/>		MUFFLER RUSTY	MISSING PARTS													
12	TRANSMISSION (AT / MT)	<input checked="" type="checkbox"/>		SHOCK	NOISE	SLIP												
OPTION																		
<input checked="" type="checkbox"/> RADIO	<input type="checkbox"/> CD	<input type="checkbox"/> DVD	<input type="checkbox"/> SUN ROOF	<input type="checkbox"/> FLIP DOWN MONITOR														
<input type="checkbox"/> REAR MONITOR	<input type="checkbox"/> BACK CAMERA	<input type="checkbox"/> CRUISE CONTROL	<input type="checkbox"/> POWER SLIDING DOOR (LEFT)	<input type="checkbox"/> POWER SLIDING DOOR (RIGHT)														
<input type="checkbox"/> POWER BACK DOOR																		
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。																		
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。																		

YARD	マツミ
------	-----

INSPECTER	吉村
-----------	----

AA SHEET	<input checked="" type="checkbox"/>
----------	-------------------------------------