

CONDITION CHECK REPORT

BF No.	BH667130	CHASSIS No.	MCU31-0004413	DATE	2020 / 12 / 26
--------	----------	-------------	---------------	------	----------------

1	TIMING BELT CHANGE	<input checked="" type="radio"/>	YES	101548	KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/>	OK	NG			NONE
2	COOLANT LEVEL	<input checked="" type="radio"/>	OK	LEAK		14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/>	OK	NG			NONE
3	ENGINE OIL LEVEL	<input checked="" type="radio"/>	OK	DIRT		15	POWER WINDOW (R REAR)	<input checked="" type="radio"/>	OK	NG			NONE
4	OIL LEAKING	<input checked="" type="radio"/>	OK	SMALL	BIG	16	POWER WINDOW (L REAR)	<input checked="" type="radio"/>	OK	NG			NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/>	OK	235/55R18	RFT	17	A/C CONDITION	<input checked="" type="radio"/>	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/>	OK	235/55R18	RFT	18	INTERIOR CONDITION	<input checked="" type="radio"/>	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/>	OK	235/55R18	RFT	19	CHECK / WARNING LAMP	<input checked="" type="radio"/>	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/>	OK	235/55R18	RFT	(COMMENT)					TESTER CHECK		
9	ENGINE NOISE	<input checked="" type="radio"/>	OK	E/G	OTHERS								
10	ENGINE CONDITION	<input checked="" type="radio"/>	OK	IDLING	SMOKE								
11	EXHAUST LEAK	<input checked="" type="radio"/>	OK	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	<input checked="" type="radio"/>	OK	SHOCK	NOISE						SLIP		
OPTION													
<input checked="" type="radio"/> RADIO		<input checked="" type="radio"/> C D		<input checked="" type="radio"/> SUN ROOF									
		<input checked="" type="radio"/> BACK CAMERA											
<input checked="" type="radio"/> POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。													

YARD	木更津・畑沢(SPX)	INSPECTER	若生	AA SHEET	✓
------	-------------	-----------	----	----------	---