

CONDITION CHECK REPORT

BF No.	BH682027	CHASSIS No.	HG21S-103990	DATE	2020 / 12 / 28
--------	----------	-------------	--------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG			NONE	
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG	LEAK			14 POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG			NONE	
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT			15 POWER WINDOW (R REAR)	<input checked="" type="radio"/> OK	NG			NONE	
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	<input checked="" type="radio"/> OK	NG			NONE	
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	155/65R13		RFT	17 A/C CONDITION	<input checked="" type="radio"/> OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE	
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	155/65R13		RFT	18 INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	155/65R13		RFT	19 CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	155/65R13		RFT	(COMMENT) CD & DVD FAILURE (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。				TESTER CHECK		
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (<input checked="" type="radio"/> AT / MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE	SLIP							
OPTION													
	<input checked="" type="radio"/> RADIO	<input checked="" type="radio"/> CD	<input checked="" type="radio"/> DVD										
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。													

YARD	大黒K号地(INTER 東商EX)	INSPECTER	寒川	AA SHEET	✓
------	-------------------	-----------	----	----------	---