

SPECS

| | | | |
|-------------------|-------------------|------------------|----------------------|
| Ref No | BH688065 | Location Country | Korea |
| Chassis # | KMCRB18TP8C024746 | Ver/Class | |
| Model Code | TRAGO | Ext.Color | Red |
| Engine Size | 12,344 cc | Fuel | Diesel |
| Drive | 4WD | Seats | 2 |
| Transmission | Manual | Doors | 2 |
| Mileage | 877,237 km | Weight | 12,250 kg |
| Engine Code | D6CB | Dimension | 8.72 × 2.49 × 3.27 m |
| Steering | Left | M3 | 71.001 |
| Registration Year | 2007 | | |
| Manufacture Year | 2007 | | |

STANDARD FEATURES

| | | | | | | | |
|----------------|---|-----------------|---|-------------------|---|--------------|---|
| CD Player | | Sun Roof | | Leather Seat | ✓ | Alloy Wheels | |
| Power Steering | ✓ | Power Window | ✓ | A/C | ✓ | ABS | ✓ |
| Airbag | ✓ | Radio | ✓ | CD Changer | | DVD | |
| TV | | Power Seat | ✓ | Back Tire | | Grill Guard | |
| Rear Spoiler | | Central Locking | | Jack | | Spare Tire | ✓ |
| Wheel Spanner | | Fog Lights | ✓ | Back Camera | | Push Start | |
| Keyless Entry | | ESC | | 360 Degree Camera | | | |
| | | | | | | | |

SUPPLIER'S CONDITION REPORT

| | | | |
|-------------------|---------|-----|------|
| Corrosion | NO | YES | |
| Under Body Holes | NO | YES | |
| Under Body Broken | NO | YES | |
| Engine | Working | NG | |
| Brake System | Working | NG | |
| Heater | Working | NG | |
| Power Window | Working | NG | |
| Transmission | Working | NG | |
| A/C | Working | NG | |
| Audio System | Working | NG | |
| 4WD | Working | NG | NONE |

COMMENTS

DATE 2020/12/28