

## CONDITION CHECK REPORT

No.	BH694903	CHASSIS No.	SK82VN-401530			DATE	2021 / 01 / 05		
-----	----------	-------------	---------------	--	--	------	----------------	--	--

  

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE	
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE	
5	TIRE (R FRONT)	OK	NG	165 / 80 R 14	RFT		17 A/C CONDITION	OK	NG		WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	165 / 80 R 14	RFT		18 INTERIOR CONDITION	OK	NG		DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	165 / 80 R 14	RFT		19 CHECK / WARNING LAMP	OK	E/G		ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	165 / 80 R 14	RFT		(COMMENT) OIL LEAKING: NG : SMALL  オイルにじみ小 ヘッド 室内汚れキズスレ シートスレ汚れ ドア内張りキズ汚れ 天張り汚れ ハンドルG不良					TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP								
OPTION														
RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR										
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)										
POWER BACK DOOR														
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。							

YARD	藤原AC第3
------	--------

INSPECTER	hanaguchi
-----------	-----------

AA SHEET	○
----------	---