

CONDITION CHECK REPORT

車種 BH	No. 696010	CHASSIS No.	NCP100-0098556			DATE	2021 2020 / 1 / 17						
1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/>	NG			NONE	
2	COOLANT LEVEL	<input checked="" type="radio"/>	NG	LEAK		14	POWER WINDOW (L FRONT)	<input checked="" type="radio"/>	NG			NONE	
3	ENGINE OIL LEVEL	<input checked="" type="radio"/>	NG	DIRT		15	POWER WINDOW (R REAR)	<input checked="" type="radio"/>	NG			NONE	
4	OIL LEAKING	<input checked="" type="radio"/>	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	<input checked="" type="radio"/>	NG			NONE	
5	TIRE (R FRONT)	<input checked="" type="radio"/>	NG	175-60 R 16	RFT	17	AIR CONDITION	<input checked="" type="radio"/>	NG	WIND BLOWS OK		NONE	
6	TIRE (L FRONT)	<input checked="" type="radio"/>	NG	/ R	RFT	18	INTERIOR CONDITION	OK	<input checked="" type="radio"/>	<input checked="" type="radio"/>	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	<input checked="" type="radio"/>	NG	/ R	RFT	19	CHECK / WARNING LAMP	<input checked="" type="radio"/>	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	<input checked="" type="radio"/>	NG	↓ / R	RFT	(COMMENT) 室内行...							
9	ENGINE NOISE	<input checked="" type="radio"/>	NG	E/G	OTHERS								
10	ENGINE CONDITION	<input checked="" type="radio"/>	NG	IDLING	SMOKE								
11	EXHAUST LEAK	<input checked="" type="radio"/>	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)	<input checked="" type="radio"/>	NG	SHOCK	NOISE							SLIP	
OPTION													
<input checked="" type="radio"/>	<input checked="" type="radio"/>												
REAR MONITOR	BACK CAMERA	CRUISE CONTROL		POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR													
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品 が付いていないものは「無印」でお願いします。													
Yard			G			Inspector			71232			AA SHEET	<input checked="" type="checkbox"/>

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。
 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで
 囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。