

CONDITION CHECK REPORT

BF No.	BH 708237	CHASSIS No.	MH23S-787747
--------	-----------	-------------	--------------

DATE 2021 / 1 / 15

1 TIMING BELT CHANGE		YES		KM	13 POWER WINDOW (R FRONT)	(OK)	NG		NONE	
2 COOLANT LEVEL	(OK)	NG	LEAK		14 POWER WINDOW (L FRONT)	(OK)	NG		NONE	
3 ENGINE OIL LEVEL	(OK)	NG	DIRT		15 POWER WINDOW (R REAR)	(OK)	NG		NONE	
4 OIL LEAKING	(OK)	NG	SMALL BIG		16 POWER WINDOW (L REAR)	(OK)	NG		NONE	
5 TIRE (R FRONT)	(OK)	NG	14580 R13	RFT	17 A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6 TIRE (L FRONT)	(OK)	NG	14580 R13	RFT	18 INTERIOR CONDITION	OK	(NG)	(DIRT)	SMOKING SMELL	OTHER SMELL
7 TIRE (R REAR)	(OK)	NG	14580 R13	RFT	19 CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER
8 TIRE (L REAR)	(OK)	NG	14580 R13	RFT	(COMMENT) TESTER CHECK					
9 ENGINE NOISE	(OK)	NG	E/G	OTHERS						
10 ENGINE CONDITION	(OK)	NG	IDLING	SMOKE						
11 EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS						
12 TRANSMISSION (AT/MT)	(OK)	NG	SHOCK	NOISE SLIP						
OPTION					(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで 囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					
(RADIO)	(CD)	DVD	SUN ROOF	FLIP DOWN MONITOR						
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)						
POWER BACK DOOR										

YARD	KANDA
------	-------

INSPECTER	柳詰
-----------	----

AA SHEET	(Signature)
----------	-------------