

# CONDITION CHECK REPORT

BH No.	7/0 2/1	CHASSIS No.	PNT 30-007529	DATE	2021 / 12 / 12
--------	---------	-------------	---------------	------	----------------

No.	Item	YES	NG	LEAK	DIRT	SMALL	BIG	RFT	Item	OK	NG	E/G	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
1	TIMING BELT CHANGE								13 POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG						14 POWER WINDOW (L FRONT)	OK	NG				NONE
3	ENGINE OIL LEVEL	OK	NG						15 POWER WINDOW (R REAR)	OK	NG				NONE
4	OIL LEAKING	OK	NG	SMALL	BIG				16 POWER WINDOW (L REAR)	OK	NG				NONE
5	TIRE (R FRONT)	OK	NG	225/55 R 17				RFT	17 A/C CONDITION	OK	NG		WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	/	R			RFT	18 INTERIOR CONDITION	OK	NG		DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	/	R			RFT	19 CHECK / WARNING LAMP	OK	E/G		ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	/	R			RFT	(COMMENT)  <div style="font-size: 1.5em; text-align: center;">モモステアリング 4WD</div>			TESTER CHECK			
9	ENGINE NOISE	OK	NG	E/G	OTHERS										
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE										
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS										
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP									
OPTION															
RADIO		DVD		SUN ROOF		FLIP DOWN MONITOR									
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)							
POWER BACK DOOR															
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。															
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。															

YARD	ECL木更津
------	--------

INSPECTER	カサハラ
-----------	------

AA SHEET	9
----------	---