

# CONDITION CHECK REPORT

BF No.	BH724741	CHASSIS No.	ZCAZ6-0026359	DATE	2021 / 1 / 25
--------	----------	-------------	---------------	------	---------------

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG		NONE	
2	COOLANT LEVEL	(OK)	NG	LEAK	14	POWER WINDOW (L FRONT)	(OK)	NG		NONE	
3	ENGINE OIL LEVEL	(OK)	NG	DIRT	15	POWER WINDOW (R REAR)	(OK)	NG		NONE	
4	OIL LEAKING	(OK)	NG	SMALL    BIG	16	POWER WINDOW (L REAR)	(OK)	NG		NONE	
5	TIRE (R FRONT)	(OK)	NG	215/70 R16	RFT	17	A/C CONDITION	(OK)	NG	WIND BLOWS OK    CAN'T OPERATE    A/C NONE	
6	TIRE (L FRONT)	(OK)	NG	215/70 R16	RFT	18	INTERIOR CONDITION	(OK)	NG	DIRT    SMOKING SMELL    OTHER SMELL	
7	TIRE (R REAR)	(OK)	NG	215/70 R16	RFT	19	CHECK / WARNING LAMP	(OK)	E/G	ABS    AIRBAG    OTHER	
8	TIRE (L REAR)	(OK)	NG	215/70 R16	RFT	(COMMENT)				TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G    OTHERS							
10	ENGINE CONDITION	(OK)	NG	IDLING    SMOKE							
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY    MISSING PARTS							
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK    NOISE    SLIP							
OPTION											
<del>RADIO</del>	<del>CD</del>	DVD	SUN ROOF	FLIP DOWN MONITOR							
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)							
POWER BACK DOOR											

(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで困る)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	KANDA	INSPECTER	柳 詰	AA SHEET	
------	-------	-----------	-----	----------	--