

CONDITION CHECK REPORT

BF No.	BH769990	CHASSIS No.	HA25V-746032
--------	----------	-------------	--------------

DATE 2021 / 2 / 16

1 TIMING BELT CHANGE		YES				13 POWER WINDOW (R FRONT)	OK	NG				NONE
2 COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE
3 ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE
4 OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE
5 TIRE (R FRONT)	OK	NG	14580	R13	RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6 TIRE (L FRONT)	OK	NG	14580	R13	RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7 TIRE (R REAR)	OK	NG	14580	R13	RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8 TIRE (L REAR)	OK	NG	14580	R13	RFT	(COMMENT)			TESTER CHECK			
9 ENGINE NOISE	OK	NG	E/G	OTHERS								
10 ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11 EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12 TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION												
RADIO	C D	DVD	SUN ROOF		FLIP DOWN MONITOR							
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)							
POWER BACK DOOR												
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						

YARD	KANDA
------	-------

INSPECTER	柳 詰
-----------	-----

AA SHEET	○
----------	---