

### SPECS

|                   |             |                  |                      |
|-------------------|-------------|------------------|----------------------|
| Ref No            | BH890952    | Location Country | United Kingdom       |
| Chassis #         | VSK13859    | Ver/Class        | Automatic Diesel     |
| Model Code        |             | Ext.Color        | Blue                 |
| Engine Size       | 2,300 cc    | Fuel             | Diesel               |
| Drive             | 4WD         | Seats            | 5                    |
| Transmission      | Automatic   | Doors            | 4                    |
| Mileage           | 37,000 mile | Weight           | 2,081 kg             |
| Engine Code       |             | Dimension        | 5.30 × 2.08 × 1.85 m |
| Steering          | Right       | M3               | 20.394               |
| Registration Year | 2016/09     |                  |                      |
| Manufacture Year  |             |                  |                      |

### STANDARD FEATURES

|                |   |                 |   |                   |   |              |   |
|----------------|---|-----------------|---|-------------------|---|--------------|---|
| CD Player      | ✓ | Sun Roof        |   | Leather Seat      |   | Alloy Wheels | ✓ |
| Power Steering | ✓ | Power Window    | ✓ | A/C               | ✓ | ABS          | ✓ |
| Airbag         | ✓ | Radio           | ✓ | CD Changer        |   | DVD          |   |
| TV             |   | Power Seat      |   | Back Tire         |   | Grill Guard  |   |
| Rear Spoiler   |   | Central Locking |   | Jack              |   | Spare Tire   |   |
| Wheel Spanner  |   | Fog Lights      |   | Back Camera       |   | Push Start   |   |
| Keyless Entry  |   | ESC             |   | 360 Degree Camera |   |              |   |
|                |   |                 |   |                   |   |              |   |

### SUPPLIER'S CONDITION REPORT

|                   |               |                |      |
|-------------------|---------------|----------------|------|
| Corrosion         | NO            | <del>YES</del> |      |
| Under Body Holes  | <del>NO</del> | YES            |      |
| Under Body Broken | <del>NO</del> | YES            |      |
| Engine            | Working       | NG             |      |
| Brake System      | Working       | NG             |      |
| Heater            | Working       | NG             |      |
| Power Window      | Working       | NG             |      |
| Transmission      | Working       | NG             |      |
| A/C               | Working       | NG             |      |
| Audio System      | Working       | NG             |      |
| 4WD               | Working       | NG             | NONE |

### COMMENTS

THERE IS NO GUARANTEE ABOUT HOLES AND BROKEN  
SOLD AS IS & SHOWN.

DATE 2021/04/01