

CONDITION CHECK REPORT

BF No.	BH919922	CHASSIS No.	CWFFW-103720	DATE	2021 / 4 / 15
--------	----------	-------------	--------------	------	---------------

1	TIMING BELT CHANGE		YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG			NONE	
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG			NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE	
5	TIRE (R FRONT)	OK	NG	195/65 R/15	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	195/65 R/15	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	195/65 R/15	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	195/65 R/15	RFT	(COMMENT) 元々3年+、3台+、工具 欠 TESTER CHECK						
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE						SLIP	
OPTION												
RADIO	CD	MP3	SUN ROOF	FLIP DOWN MONITOR								
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR												
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願いします。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD		INSPECTER	千賀
		AA SHEET	0