

CONDITION CHECK REPORT

BH No.	922570	CHASSIS No.	G11-050197
--------	--------	-------------	------------

DATE 2021/ 4/ 9

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE		
2	COOLANT LEVEL	OK	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE		
3	ENGINE OIL LEVEL	OK	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE		
4	OIL LEAKING	OK	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG		NONE		
5	TIRE (R FRONT)	OK	185/65 R15	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	/	R	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	/	R	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	X	R	RFT	(COMMENT) スタートキー シート・ハンドル汚れ 10ヶ所跡			TESTER CHECK			
9	ENGINE NOISE	OK	E/G	OTHERS								
10	ENGINE CONDITION	OK	IDLING	SMOKE								
11	EXHAUST LEAK	OK	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT/MT)	OK	SHOCK	NOISE	SLIP							
OPTION												
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR								
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR												

(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD	ECL 富津
------	--------

INSPECTER	人ノミ
-----------	-----

AA SHEET	O
----------	---