

SPECS

| | | | |
|-------------------|-------------|------------------|----------------------|
| Ref No | BH933129 | Location Country | United Kingdom |
| Chassis # | JTE5962 | Ver/Class | MANUAL DIESEL |
| Model Code | | Ext.Color | Silver |
| Engine Size | 1,400 cc | Fuel | Diesel |
| Drive | 4WD | Seats | 5 |
| Transmission | Manual | Doors | 5 |
| Mileage | 78,344 mile | Weight | |
| Engine Code | | Dimension | 3.95 × 1.80 × 1.65 m |
| Steering | Right | M3 | 11.732 |
| Registration Year | 2010/11 | | |
| Manufacture Year | | | |

STANDARD FEATURES

| | | | | | | | |
|----------------|---|-----------------|---|-------------------|---|--------------|---|
| CD Player | ✓ | Sun Roof | | Leather Seat | | Alloy Wheels | ✓ |
| Power Steering | ✓ | Power Window | ✓ | A/C | ✓ | ABS | ✓ |
| Airbag | ✓ | Radio | ✓ | CD Changer | | DVD | |
| TV | | Power Seat | | Back Tire | | Grill Guard | |
| Rear Spoiler | | Central Locking | | Jack | | Spare Tire | |
| Wheel Spanner | | Fog Lights | | Back Camera | | Push Start | |
| Keyless Entry | | ESC | | 360 Degree Camera | | | |
| | | | | | | | |

SUPPLIER'S CONDITION REPORT

| | | | |
|-------------------|---------|-----|------|
| Corrosion | NO | YES | |
| Under Body Holes | NO | YES | |
| Under Body Broken | NO | YES | |
| Engine | Working | NG | |
| Brake System | Working | NG | |
| Heater | Working | NG | |
| Power Window | Working | NG | |
| Transmission | Working | NG | |
| A/C | Working | NG | |
| Audio System | Working | NG | |
| 4WD | Working | NG | NONE |

COMMENTS

THERE IS NO GUARANTEE ABOUT HOLES AND BROKEN

SOLD AS IS & SHOWN

DATE 2021/04/18