

CONDITION CHECK REPORT

BF No.	BH929483	CHASSIS No.	WVWZZZAUZEW009539	DATE	2021 / 4 / 26
--------	----------	-------------	-------------------	------	---------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/>	NG			NONE
2	COOLANT LEVEL	<input checked="" type="radio"/>	NG	LEAK			14 POWER WINDOW (L FRONT)	<input checked="" type="radio"/>	NG			NONE
3	ENGINE OIL LEVEL	<input checked="" type="radio"/>	NG	DIRT			15 POWER WINDOW (R REAR)	<input checked="" type="radio"/>	NG			NONE
4	OIL LEAKING	<input checked="" type="radio"/>	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	<input checked="" type="radio"/>	NG			NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/>	NG	195/65R15		RFT	17 A/C CONDITION	<input checked="" type="radio"/>	NG	WIND BLOWS OK	CAN'T OPERATE	NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/>	NG	195/65R15		RFT	18 INTERIOR CONDITION	<input checked="" type="radio"/>	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/>	NG	195/65R15		RFT	19 CHECK / WARNING LAMP	<input checked="" type="radio"/>	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/>	NG	195/65R15		RFT	(COMMENT) RADIO & CD & DVD FAILURE				TESTER CHECK	
9	ENGINE NOISE	<input checked="" type="radio"/>	NG	E/G	OTHERS							
10	ENGINE CONDITION	<input checked="" type="radio"/>	NG	IDLING	SMOKE							
11	EXHAUST LEAK	<input checked="" type="radio"/>	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (<input checked="" type="radio"/> AT) / MT)	<input checked="" type="radio"/>	NG	SHOCK	NOISE	SLIP						
OPTION												
<input checked="" type="radio"/> RADIO		<input checked="" type="radio"/> CD		<input checked="" type="radio"/> DVD								
							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					

YARD	木更津・畑沢(SPX)
------	-------------

INSPECTER	NODA
-----------	------

AA SHEET	✓
----------	---