

## CONDITION CHECK REPORT

|        |        |             |             |      |           |
|--------|--------|-------------|-------------|------|-----------|
| BH No. | 9355/2 | CHASSIS No. | RM1-1000/60 | DATE | 2021/4/27 |
|--------|--------|-------------|-------------|------|-----------|

|                 |                        |                |                           |                            |               |      |   |                        |    |     |               |               |             |  |
|-----------------|------------------------|----------------|---------------------------|----------------------------|---------------|------|---|------------------------|----|-----|---------------|---------------|-------------|--|
| 1               | TIMING BELT CHANGE     |                | YES                       |                            |               | KM   | 13  | POWER WINDOW (R FRONT) | OK | NG  |               |               | NONE        |  |
| 2               | COOLANT LEVEL          | OK             | NG                        | LEAK                       |               |      | 14  | POWER WINDOW (L FRONT) | OK | NG  |               |               | NONE        |  |
| 3               | ENGINE OIL LEVEL       | OK             | NG                        | DIRT                       |               |      | 15  | POWER WINDOW (R REAR)  | OK | NG  |               |               | NONE        |  |
| 4               | OIL LEAKING            | OK             | NG                        | SMALL                      | BIG           |      | 16  | POWER WINDOW (L REAR)  | OK | NG  |               |               | NONE        |  |
| 5               | TIRE (R FRONT)         | OK             | NG                        | 225/65 R/19                |               | RFT  | 17  | A/C CONDITION          | OK | NG  | WIND BLOWS OK | CAN'T OPERATE | A/C NONE    |  |
| 6               | TIRE (L FRONT)         | OK             | NG                        | /                          | R             | RFT  | 18  | INTERIOR CONDITION     | OK | NG  | DIRT          | SMOKING SMELL | OTHER SMELL |  |
| 7               | TIRE (R REAR)          | OK             | NG                        | /                          | R             | RFT  | 19  | CHECK / WARNING LAMP   | OK | E/G | ABS           | AIRBAG        | OTHER       |  |
| 8               | TIRE (L REAR)          | OK             | NG                        | /                          | R             | RFT  | (COMMENT)<br><br><div style="font-size: 1.2em; text-align: center;">                     70% システム<br/>                     22-17-<br/>                     Auto シフト<br/>                     車内 汚れ                 </div> |                        |    |     |               | TESTER CHECK  |             |  |
| 9               | ENGINE NOISE           | OK             | NG                        | E/G                        | OTHERS        |      |   |                        |    |     |               |               |             |  |
| 10              | ENGINE CONDITION       | OK             | NG                        | IDLING                     | SMOKE         |      |   |                        |    |     |               |               |             |  |
| 11              | EXHAUST LEAK           | OK             | NG                        | MUFFLER RUSTY              | MISSING PARTS |      |   |                        |    |     |               |               |             |  |
| 12              | TRANSMISSION (AT / MT) | OK             | NG                        | SHOCK                      | NOISE         | SLIP |   |                        |    |     |               |               |             |  |
| OPTION          |                        |                |                           |                            |               |      |   |                        |    |     |               |               |             |  |
| RADIO           | CD                     | DVD            | SUN ROOF                  | FLIP DOWN MONITOR          |               |      |   |                        |    |     |               |               |             |  |
| REAR MONITOR    | BACK CAMERA            | CRUISE CONTROL | POWER SLIDING DOOR (LEFT) | POWER SLIDING DOOR (RIGHT) |               |      |   |                        |    |     |               |               |             |  |
| POWER BACK DOOR |                        |                |                           |                            |               |      |   |                        |    |     |               |               |             |  |

(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

|      |        |           |     |          |   |
|------|--------|-----------|-----|----------|---|
| YARD | ECL 富津 | INSPECTER | 123 | AA SHEET | 0 |
|------|--------|-----------|-----|----------|---|