

CONDITION CHECK REPORT

| | | | | | |
|--------|----------|-------------|----------------------|------|---------------|
| BF No. | BH941956 | CHASSIS No. | WUG222 7L ZAD 023246 | DATE | 2021 / 4 / 22 |
|--------|----------|-------------|----------------------|------|---------------|

| | | | | | | | | | | | | | |
|---|----------------------|-------------------------------------|----------------|---------------|---------------------------|------|----------------------------------|-------------------------------------|-----|---|---------------|---|------|
| 1 | TIMING BELT CHANGE | | YES | | KM | 13 | POWER WINDOW (R FRONT) | <input checked="" type="checkbox"/> | NG | | | | NONE |
| 2 | COOLANT LEVEL | <input checked="" type="checkbox"/> | NG | LEAK | | | 14 POWER WINDOW (L FRONT) | <input checked="" type="checkbox"/> | NG | | | | NONE |
| 3 | ENGINE OIL LEVEL | <input checked="" type="checkbox"/> | NG | DIRT | | | 15 POWER WINDOW (R REAR) | <input checked="" type="checkbox"/> | NG | | | | NONE |
| 4 | OIL LEAKING | <input checked="" type="checkbox"/> | NG | SMALL | BIG | | 16 POWER WINDOW (L REAR) | <input checked="" type="checkbox"/> | NG | | | | NONE |
| 5 | TIRE (R FRONT) | <input checked="" type="checkbox"/> | NG | 255/60 R17 | RFT | | 17 A/C CONDITION | <input checked="" type="checkbox"/> | NG | WIND BLOWS OK | CAN'T OPERATE | A/C NONE | |
| 6 | TIRE (L FRONT) | <input checked="" type="checkbox"/> | NG | 255/60 R17 | RFT | | 18 INTERIOR CONDITION | <input checked="" type="checkbox"/> | NG | DIRT | SMOKING SMELL | OTHER SMELL | |
| 7 | TIRE (R REAR) | <input checked="" type="checkbox"/> | NG | 255/60 R17 | RFT | | 19 CHECK / WARNING LAMP | <input checked="" type="checkbox"/> | E/G | <input checked="" type="checkbox"/> ABS | AIRBAG | <input checked="" type="checkbox"/> OTHER | |
| 8 | TIRE (L REAR) | <input checked="" type="checkbox"/> | NG | 255/60 R17 | RFT | | (COMMENT) ESPランプ点灯 7, 2枚あり | | | | | TESTER CHECK | |
| 9 | ENGINE NOISE | <input checked="" type="checkbox"/> | NG | E/G | OTHERS | | | | | | | | |
| 10 | ENGINE CONDITION | <input checked="" type="checkbox"/> | NG | IDLING | SMOKE | | | | | | | | |
| 11 | EXHAUST LEAK | <input checked="" type="checkbox"/> | NG | MUFFLER RUSTY | MISSING PARTS | | | | | | | | |
| 12 | TRANSMISSION (AT/MT) | <input checked="" type="checkbox"/> | NG | SHOCK | NOISE | SLIP | | | | | | | |
| OPTION | | | | | | | | | | | | | |
| RADIO | | <input checked="" type="checkbox"/> | DVD | | SUN ROOF | | FLIP DOWN MONITOR | | | | | | |
| REAR MONITOR | | <input checked="" type="checkbox"/> | CRUISE CONTROL | | POWER SLIDING DOOR (LEFT) | | POWER SLIDING DOOR (RIGHT) | | | | | | |
| POWER BACK DOOR | | | | | | | | | | | | | |
| (注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」でお願いします。 | | | | | | | | | | | | | |
| (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。 | | | | | | | | | | | | | |

| | | | | | |
|------|--|-----------|----|----------|---|
| YARD | | INSPECTER | 千賀 | AA SHEET | Q |
|------|--|-----------|----|----------|---|