

# CONDITION CHECK REPORT

DATE 2021/ 4/ 28

BH No.	942436	CHASSIS No.	GRS191-0005414
--------	--------	-------------	----------------

No.	Item	OK	NG	LEAK	DIRT	SMALL	BIG	RFT	KM	13	POWER WINDOW (R FRONT)	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C	NONE							
																		14	POWER WINDOW (L FRONT)	OK	NG	15	POWER WINDOW (R REAR)	OK
1	TIMING BELT CHANGE																							
2	COOLANT LEVEL	OK	NG																					
3	ENGINE OIL LEVEL	OK	NG																					
4	OIL LEAKING	OK	NG																					
5	TIRE (R FRONT)	OK	NG	225 / 35			R 20	RFT																
6	TIRE (L FRONT)	OK	NG	/			R	RFT																
7	TIRE (R REAR)	OK	NG	/			R	RFT																
8	TIRE (L REAR)	OK	NG	/			R	RFT																
9	ENGINE NOISE	OK	NG			E/G	OTHERS																	
10	ENGINE CONDITION	OK	NG			IDLING	SMOKE																	
11	EXHAUST LEAK	OK	NG			MUFFLER RUSTY	MISSING PARTS																	
12	TRANSMISSION (AT / MT)	OK	NG			SHOCK	NOISE	SLIP																
(COMMENT)																								
<p style="font-size: 1.5em; font-weight: bold;">* push up!</p> <p style="font-size: 1.5em; font-weight: bold;">* 207-31</p> <p style="font-size: 1.5em; font-weight: bold;">AFS 新</p> <p style="font-size: 1.5em; font-weight: bold;">440 新</p> <p style="font-size: 1.5em; font-weight: bold;">370 新</p> <p style="font-size: 1.5em; font-weight: bold;">タフエハダ</p> <p style="font-size: 1.5em; font-weight: bold;">シズ</p> <p style="font-size: 1.5em; font-weight: bold;">Fダシロ 新</p>																								
TESTER CHECK																								

OPTION					
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR	
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)	
POWER BACK DOOR					

(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD ECL 富津

INSPECTER [Signature]

AA SHEET 9