

# CONDITION CHECK REPORT

BH No.	945277	CHASSIS No.	ANH10-0039027
--------	--------	-------------	---------------

DATE 2021/ 4 / 30

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK			POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	<del>OK</del>	NG	SMALL	BIG		POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	205 / 65 R 16	RFT		A/G CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/G NONE
6	TIRE (L FRONT)	OK	NG	/ R	RFT		INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	↓ R	RFT		19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	/ R	RFT		(COMMENT)	ホト3外 ナセ画面ケル 打刻カビ-欠品				
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (A/MT)	OK	NG	SHOCK	NOISE	SLIP						
OPTION												
	RADIO	OK		DVD	SUN ROOF	FLIP DOWN MONITOR						
	REAR MONITOR	OK		CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)						
	POWER BACK DOOR	OK										
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD	ECL 富津
------	--------

INSPECTER	カサハシ
-----------	------

AA SHEET	9
----------	---