

CONDITION CHECK REPORT

# No. **BK** 005029 CHASSIS No. **GRS182-1039030**

DATE **2021/4/30**

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	OK	NG	NONE
2	COOLANT LEVEL	OK	NG	LEAK	14	POWER WINDOW (L FRONT)	OK	NG	NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT	15	POWER WINDOW (R REAR)	OK	NG	NONE
4	OIL LEAKING	OK	NG	SMALL BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE
5	TIRE (R FRONT)	OK	NG	225/30 R 20 RFT	17	AIR CONDITION	OK	NG	WIND BLOWS OK NONE
6	TIRE (L FRONT)	OK	NG	/ ↓ R RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	245/30 R 20 RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	/ ↓ RFT	(COMMENT) ・Rミラー (R) 格系内不良 ・ハンドル・スレ ・ダッシュ板・キレ・ハゲ ・テーブル・ゼス取り付け				
9	ENGINE NOISE	OK	NG	E/G OTHERS					
10	ENGINE CONDITION	OK	NG	IDLING SMOKE					
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY MISSING PARTS					
12	TRANSMISSION (AT MT)	OK	NG	SHOCK NOISE SLIP					
OPTION RADIO REAR MONITOR POWER BACK DOOR CD BACK CAMERA DVD CRUISE CONTROL SUN ROOF POWER SLIDING DOOR (LEFT) FLIP DOWN MONITOR POWER SLIDING DOOR (RIGHT)					(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オプションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやエッジ(マークで示して)、その他目立つ症状部分があった場合は、写真撮影をお願いします。				

Yard **ECL新門司** Inspector **KK2** AA SHEET