

## SPECS

|                   |                   |                  |                      |
|-------------------|-------------------|------------------|----------------------|
| Ref No            | BK020117          | Location Country | Korea                |
| Chassis #         | SALFA2BC0AH182420 | Ver/Class        | SUNROOF SMART KEY    |
| Model Code        |                   | Ext.Color        | Black                |
| Engine Size       | 2,179 cc          | Fuel             | Diesel               |
| Drive             | 4WD               | Seats            | 5                    |
| Transmission      | Automatic         | Doors            | 5                    |
| Mileage           | 207,555 km        | Weight           | 1,910 kg             |
| Engine Code       |                   | Dimension        | 4.51 × 1.91 × 1.75 m |
| Steering          | Left              | M3               | 15.075               |
| Registration Year | 2010              |                  |                      |
| Manufacture Year  |                   |                  |                      |

## STANDARD FEATURES

|                |   |                 |   |                   |   |              |   |
|----------------|---|-----------------|---|-------------------|---|--------------|---|
| CD Player      | ✓ | Sun Roof        | ✓ | Leather Seat      | ✓ | Alloy Wheels | ✓ |
| Power Steering | ✓ | Power Window    | ✓ | A/C               | ✓ | ABS          | ✓ |
| Airbag         | ✓ | Radio           | ✓ | CD Changer        |   | DVD          |   |
| TV             | ✓ | Power Seat      | ✓ | Back Tire         |   | Grill Guard  |   |
| Rear Spoiler   |   | Central Locking | ✓ | Jack              | ✓ | Spare Tire   | ✓ |
| Wheel Spanner  | ✓ | Fog Lights      | ✓ | Back Camera       | ✓ | Push Start   | ✓ |
| Keyless Entry  | ✓ | ESC             |   | 360 Degree Camera |   |              |   |
|                |   |                 |   |                   |   |              |   |

## SUPPLIER'S CONDITION REPORT

|                   |         |     |      |
|-------------------|---------|-----|------|
| Corrosion         | NO      | YES |      |
| Under Body Holes  | NO      | YES |      |
| Under Body Broken | NO      | YES |      |
| Engine            | Working | NG  |      |
| Brake System      | Working | NG  |      |
| Heater            | Working | NG  |      |
| Power Window      | Working | NG  |      |
| Transmission      | Working | NG  |      |
| A/C               | Working | NG  |      |
| Audio System      | Working | NG  |      |
| 4WD               | Working | NG  | NONE |

## COMMENTS

Front Glass crack

DATE 2021/07/22