CONDITION CHECK REPORT

No.	BK029465	CHASSIS No.	WVWZZZ1KZ-AM671281	DATE	2021 / 05 / 14

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK		14	POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT		15	POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	205 / 55 R 16	RFT	17	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	205 / 55 R 16	RFT	18	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	205 / 55 R 16	RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	205 / 55 R 16	RFT					TESTER CHECK		
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP						

(COMMENT)

シート汚れ。
内張りうき。
ハンドルスレ。

OPTION

RADIO	C D	DVD	SUN ROOF	FLIP DOWN MONITOR
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)
POWER BACK DOOR				

(注意) オプション品が付いていて作動するものは「○」、 付いていて作動しないものは「×」、
オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載お願いします。
オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影お願いします。

YARD	藤原ＡＣ第３	INSPECTER	fudano	AA SHEET	○

Condition Check Report Ver6.4