

CONDITION CHECK REPORT

BF No.	BK043081	CHASSIS No.	MH23S-949089	DATE	2021 / 5 / 22
--------	----------	-------------	--------------	------	---------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE			
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE			
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE			
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE			
5	TIRE (R FRONT)	OK	NG	145/80R13		RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE		NONE			
6	TIRE (L FRONT)	OK	NG	145/80R13		RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL				
7	TIRE (R REAR)	OK	NG	145/80R13		RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER				
8	TIRE (L REAR)	OK	NG	145/80R13		RFT	(COMMENT)				TESTER CHECK					
9	ENGINE NOISE	OK	NG	E/G	OTHERS											
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE											
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS											
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP										
OPTION																
RADIO		C D														
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。																
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。																

YARD	木更津・畑沢(SPX)	INSPECTER	ITO	AA SHEET	✓
------	-------------	-----------	-----	----------	---