

SPECS

| | | | |
|-------------------|---------------|------------------|----------------------|
| Ref No | BK081596 | Location Country | UAE |
| Chassis # | FK728G-540016 | Ver/Class | |
| Model Code | Fuso | Ext.Color | White |
| Engine Size | 8,200 cc | Fuel | Diesel |
| Drive | 2WD | Seats | 3 |
| Transmission | Manual | Doors | 2 |
| Mileage | 121,214 km | Weight | 4,638 kg |
| Engine Code | | Dimension | 7.69 × 2.33 × 2.82 m |
| Steering | Right | M3 | 50.528 |
| Registration Year | 1998/05 | | |
| Manufacture Year | | | |

STANDARD FEATURES

| | | | | | | | |
|----------------|---|-----------------|---|-------------------|---|--------------|--|
| CD Player | | Sun Roof | | Leather Seat | | Alloy Wheels | |
| Power Steering | ✓ | Power Window | | A/C | ✓ | ABS | |
| Airbag | | Radio | ✓ | CD Changer | | DVD | |
| TV | | Power Seat | | Back Tire | | Grill Guard | |
| Rear Spoiler | | Central Locking | | Jack | ✓ | Spare Tire | |
| Wheel Spanner | ✓ | Fog Lights | | Back Camera | | Push Start | |
| Keyless Entry | | ESC | | 360 Degree Camera | | | |
| | | | | | | | |

SUPPLIER'S CONDITION REPORT

| | | | |
|-------------------|---------|-----|------|
| Corrosion | NO | YES | |
| Under Body Holes | NO | YES | |
| Under Body Broken | NO | YES | |
| Engine | Working | NG | |
| Brake System | Working | NG | |
| Heater | Working | NG | |
| Power Window | Working | NG | |
| Transmission | Working | NG | |
| A/C | Working | NG | |
| Audio System | Working | NG | |
| 4WD | Working | NG | NONE |

COMMENTS

DATE 2021/06/07