

# CONDITION CHECK REPORT

BF No.	BK092028	CHASSIS No.	1J8F7F8W87A333561	DATE	2021 / 6 / 17
--------	----------	-------------	-------------------	------	---------------

1 TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE	
2 COOLANT LEVEL	(OK)	NG	LEAK			14 POWER WINDOW (L FRONT)	(OK)	NG			NONE	
3 ENGINE OIL LEVEL	(OK)	NG	DIRT			15 POWER WINDOW (R REAR)	(OK)	NG			NONE	
4 OIL LEAKING	(OK)	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	(OK)	NG			NONE	
5 TIRE (R FRONT)	(OK)	NG	215/60 R17		RFT	17 A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6 TIRE (L FRONT)	(OK)	NG	215 60 R17		RFT	18 INTERIOR CONDITION	OK	(NG)	(DIRT)	SMOKING SMELL	OTHER SMOEL	
7 TIRE (R REAR)	(OK)	NG	215 60 R17		RFT	19 CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER	
8 TIRE (L REAR)	(OK)	NG	215 60 R17		RFT	(COMMENT) 左電格不良 113A→ドL足欠					TESTER CHECK	
9 ENGINE NOISE	(OK)	NG	E/G	OTHERS								
10 ENGINE CONDITION	(OK)	NG	IDLING	SMOKE								
11 EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS								
12 TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE	SLIP							
OPTION												
(RADIO)	(CD)	DVD	SUN ROOF	FLIP DOWN MONITOR								
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
POWER BACK DOOR												
(注意) オプション品が付いていて作動するのは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカ-で囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD	KANDA	INSPECTER	柳 詰	AA SHEET	○
------	-------	-----------	-----	----------	---