

CONDITION CHECK REPORT

No.	BK095239	CHASSIS No.	WBAUF12-010PN28265	DATE	2021 / 06 / 12
-----	----------	-------------	--------------------	------	----------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	OK	NG				NONE
2	COOLANT LEVEL	OK	NG	LEAK			14 POWER WINDOW (L FRONT)	OK	NG				NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG				NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	OK	NG				NONE
5	TIRE (R FRONT)	OK	NG	195 / 55 R 16	RFT		17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE	
6	TIRE (L FRONT)	OK	NG	195 / 55 R 16	RFT		18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL	
7	TIRE (R REAR)	OK	NG	195 / 55 R 16	RFT		19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER	
8	TIRE (L REAR)	OK	NG	195 / 55 R 16	RFT		(COMMENT) POWER WINDOW LEFT FRONT: NG AC: NG : WIND BLOWS OK 左リア窓不良。 AC冷えない。 チェックランプ点灯リセット不可					TESTER CHECK	○
9	ENGINE NOISE	OK	NG	E/G	OTHERS								
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE								
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS								
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP							
OPTION													
	RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR								
	REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)								
	POWER BACK DOOR												
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。						

YARD	藤原AC第3
------	--------

INSPECTER	Furukawa
-----------	----------

AA SHEET	○
----------	---