

CONDITION CHECK REPORT

BK No.	144381	CHASSIS No.	HDB50 - 0101042	DATE	2021 / 7 / 10
--------	--------	-------------	-----------------	------	---------------

1	TIMING BELT CHANGE	YES	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE	
2	COOLANT LEVEL	OK	LEAK		14	POWER WINDOW (L FRONT)	OK	NG		NONE	
3	ENGINE OIL LEVEL	OK	DIRT		15	POWER WINDOW (R REAR)	OK	NG		NONE	
4	OIL LEAKING	OK	NG	SMALL	BIG	16	POWER WINDOW (L REAR)	OK	NG	NONE	
5	TIRE (R FRONT)	OK	NG	215/70R17.5 RFT		17	A/C CONDITION	OK	NG	WIND FLOWS OK CAN'T OPERATE A/C NONE	
6	TIRE (L FRONT)	OK	NG	/	R RFT	18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL	
7	TIRE (R REAR)	OK	NG	/	R RFT	19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER	
8	TIRE (L REAR)	OK	NG	/	R RFT	(COMMENT) <div style="font-size: 24px; text-align: center;"> バス MT車 車内汚れ 腐食車 </div> <div style="font-size: 24px; text-align: right; margin-top: 20px;"> AC不良 シートキレ </div>				TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS						
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE						
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS						
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE SLIP						
OPTION											
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR							
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)							
POWER BACK DOOR											
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					

YARD	ECL木更津
------	--------

INSPECTER	/ 2 / ミ
-----------	---------

AA SHEET	0
----------	---