

CONDITION CHECK REPORT

BF No.	BK189716	CHASSIS No.	KZH1201003849	DATE	2021 / 7 / 29
--------	----------	-------------	---------------	------	---------------

1	TIMING BELT CHANGE		YES	270919	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE			
2	COOLANT LEVEL	OK	NG	LEAK			POWER WINDOW (L FRONT)	OK	NG			NONE			
3	ENGINE OIL LEVEL	OK	NG	DIRT			POWER WINDOW (R REAR)	OK	NG			NONE			
4	OIL LEAKING	OK	NG	SMALL	BIG		POWER WINDOW (L REAR)	OK	NG			NONE			
5	TIRE (R FRONT)	OK	NG	195/80R15	RFT		A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE			
6	TIRE (L FRONT)	OK	NG	195/80R15	RFT		INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL			
7	TIRE (R REAR)	OK	NG	195/80R15	RFT		CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER			
8	TIRE (L REAR)	OK	NG	195/80R15	RFT		(COMMENT) OIL LEAK SMALL FLIP DOWN MONITOR FAILURE				TESTER CHECK				
9	ENGINE NOISE	OK	NG	E/G	OTHERS										
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE										
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS										
12	TRANSMISSION ((AT) / MT)	OK	NG	SHOCK	NOISE	SLIP									
OPTION															
	RADIO						FLIP DOWN MONITOR								
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。															
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。															

YARD	木更津・畑沢(SPX)	INSPECTER	佐久間	AA SHEET	✓
------	-------------	-----------	-----	----------	---