

# CONDITION CHECK REPORT

|        |          |             |             |      |               |
|--------|----------|-------------|-------------|------|---------------|
| BF No. | BK257170 | CHASSIS No. | DY3W-327544 | DATE | 2021 / 8 / 27 |
|--------|----------|-------------|-------------|------|---------------|

|  |                          |     |     |               |               |      |  |    |     |               |               |             |  |
|--|--------------------------|-----|-----|---------------|---------------|------|--|----|-----|---------------|---------------|-------------|--|
| 1  | TIMING BELT CHANGE       |     | YES |               | KM            | 13   | POWER WINDOW (R FRONT)                                 | OK | NG  |               |               | NONE        |  |
| 2  | COOLANT LEVEL            | OK  | NG  | LEAK          |               |      | 14 POWER WINDOW (L FRONT)                              | OK | NG  |               |               | NONE        |  |
| 3  | ENGINE OIL LEVEL         | OK  | NG  | DIRT          |               |      | 15 POWER WINDOW (R REAR)                               | OK | NG  |               |               | NONE        |  |
| 4  | OIL LEAKING              | OK  | NG  | SMALL         | BIG           |      | 16 POWER WINDOW (L REAR)                               | OK | NG  |               |               | NONE        |  |
| 5  | TIRE (R FRONT)           | OK  | NG  | 175/65R14     | RFT           |      | 17 A/C CONDITION                                       | OK | NG  | WIND BLOWS OK | CAN'T OPERATE | NONE        |  |
| 6  | TIRE (L FRONT)           | OK  | NG  | 175/65R14     | RFT           |      | 18 INTERIOR CONDITION                                  | OK | NG  | DIRT          | SMOKING SMELL | OTHER SMELL |  |
| 7  | TIRE (R REAR)            | OK  | NG  | 175/65R14     | RFT           |      | 19 CHECK / WARNING LAMP                                | OK | E/G | ABS           | AIRBAG        | OTHER       |  |
| 8  | TIRE (L REAR)            | OK  | NG  | 175/65R14     | RFT           |      | (COMMENT)<br>OIL LEAK SMALL<br>LEFT FRONT P/W FAILUIRE |    |     |               | TESTER CHECK  |             |  |
| 9  | ENGINE NOISE             | OK  | NG  | E/G           | OTHERS        |      |  |    |     |               |               |             |  |
| 10   | ENGINE CONDITION         | OK  | NG  | IDLING        | SMOKE         |      |  |    |     |               |               |             |  |
| 11   | EXHAUST LEAK             | OK  | NG  | MUFFLER RUSTY | MISSING PARTS |      |  |    |     |               |               |             |  |
| 12   | TRANSMISSION ((AT) / MT) | OK  | NG  | SHOCK         | NOISE         | SLIP |  |    |     |               |               |             |  |
| OPTION   |                          |     |     |               |               |      |  |    |     |               |               |             |  |
|  | RADIO                    | C D |     |               |               |      |  |    |     |               |               |             |  |
| (注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。  |                          |     |     |               |               |      |  |    |     |               |               |             |  |
| (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。 |                          |     |     |               |               |      |  |    |     |               |               |             |  |

|      |             |
|------|-------------|
| YARD | 木更津・畑沢(SPX) |
|------|-------------|

|           |     |
|-----------|-----|
| INSPECTER | 海老根 |
|-----------|-----|

|          |   |
|----------|---|
| AA SHEET | ✓ |
|----------|---|