

CONDITION CHECK REPORT

DATE 2021 / 8 / 28

BK No.	258A32.	CHASSIS No.	KNP 90-5075636
--------	---------	-------------	----------------

No.	Item	Status		Leak/Condition		Tire	Lamp	Window	A/C	Other		
		OK	NG	SMALL	BIG					WIND BLOWS OK	CAN'T OPERATE	A/C
1	TIMING BELT CHANGE		YES									NONE
2	COOLANT LEVEL	OK	NG	LEAK								NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT								NONE
4	OIL LEAKING	OK	NG	SMALL	BIG							NONE
5	TIRE (R FRONT)	OK	NG	165/70 R14	RFT							NONE
6	TIRE (L FRONT)	OK	NG	↓	R	RFT						NONE
7	TIRE (R REAR)	OK	NG	↓	R	RFT						NONE
8	TIRE (L REAR)	OK	NG	↓	R	RFT						NONE
9	ENGINE NOISE	OK	NG	E/G	OTHERS							NONE
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							NONE
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							NONE
12	TRANSMISSION (A / MT)	OK	NG	SHOCK	NOISE	SLIP						NONE
OPTION												
	RADIO		CD	DVD	SUN ROOF	FLIP DOWN MONITOR						
	REAR MONITOR		BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)						
	POWER BACK DOOR											
(COMMENT)												
<p style="font-size: 2em; font-weight: bold;">OK 27!</p> <p style="font-size: 1.5em; font-weight: bold;">外装確認 = 1/20 = 3/4</p>												

(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD ECL 富津

INSPECTOR [Signature]

AA SHEET 9