

CONDITION CHECK REPORT

BK No.	270255	CHASSIS No.	RK5-1320958	DATE	2021 / 1 / 3
--------	--------	-------------	-------------	------	--------------

1	TIMING BELT CHANGE	YES		KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK		14 POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT		15 POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK		BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	2.5/55 R17	RFT	17 A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE
6	TIRE (L FRONT)	OK	NG	↓ R	RFT	18 INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	↓ R	RFT	19 CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	↓ R	RFT	(COMMENT) <div style="font-size: 2em; font-weight: bold; text-align: center;"> 双ホキ! 3ホキ! 3ホキ </div>		TESTER CHECK <div style="font-size: 1.5em; font-weight: bold; text-align: center;"> 3ホキ 12ホキ </div>			
9	ENGINE NOISE	OK	NG	E/G	OTHERS						
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE						
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS						
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE						SLIP
OPTION											
RADIO		CD		DVD		SUN ROOF		FLIP DOWN MONITOR			
REAR MONITOR		BACK CAMERA		CRUISE CONTROL		POWER SLIDING DOOR (LEFT)		POWER SLIDING DOOR (RIGHT)			
POWER BACK DOOR											
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					

YARD	ECL 富津	INSPECTER	[Signature]	AA SHEET	9
------	--------	-----------	-------------	----------	---