

# CONDITION CHECK REPORT

BF No. <u>BK273468</u>	CHASSIS No. <u>PE52-050506</u>	DATE <u>2021 / 9 / 16</u>
------------------------	--------------------------------	---------------------------

1	TIMING BELT CHANGE	YES		KM	13 POWER WINDOW (R FRONT)	(OK)	NG		NONE	
2	COOLANT LEVEL	(OK)	NG	LEAK	14 POWER WINDOW (L FRONT)	(OK)	NG		NONE	
3	ENGINE OIL LEVEL	(OK)	NG	DIRT	15 POWER WINDOW (R REAR)	(OK)	NG		NONE	
4	OIL LEAKING	(OK)	NG	SMALL	BIG	16 POWER WINDOW (L REAR)	(OK)	NG	NONE	
5	TIRE (R FRONT)	(OK)	NG	225/55 R18	RFT	17 A/C CONDITION	OK	(NG)	WIND BLOWS OK CAN'T OPERATE A/C NONE	
6	TIRE (L FRONT)	(OK)	NG	225/55 R18	RFT	18 INTERIOR CONDITION	(OK)	NG	DIRT SMOKING SMELL OTHER SMELL	
7	TIRE (R REAR)	(OK)	NG	225/55 R18	RFT	19 CHECK / WARNING LAMP	(OK)	E/G	ABS AIRBAG OTHER	
8	TIRE (L REAR)	(OK)	NG	225/55 R18	RFT	(COMMENT)  <div style="font-size: 2em; text-align: center;">シキキ</div>			TESTER CHECK	
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS					
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE					
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS					
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE SLIP					
OPTION										
(OK) RADIO	(OK) C/D	(OK) DVD	SUN ROOF	FLIP DOWN MONITOR						
REAR MONITOR	BACK CAMERA	(OK) CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)						
(OK) POWER BACK DOOR										
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。										
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。										

YARD	KANDA	INSPECTER	柳 詰	AA SHEET	(OK)
------	-------	-----------	-----	----------	------