

CONDITION CHECK REPORT

| | | | | | |
|--------|----------|-------------|-------------|------|--------------|
| BF No. | BK280787 | CHASSIS No. | GK3-3017318 | DATE | 2021 / 9 / 6 |
|--------|----------|-------------|-------------|------|--------------|

| | | | | | | | | | | | | |
|--|--------------------------|-----|-----|---------------|---------------|------|---------------------------|----|-----|---------------|---------------|-------------|
| 1 | TIMING BELT CHANGE | | YES | | KM | 13 | POWER WINDOW (R FRONT) | OK | NG | | | NONE |
| 2 | COOLANT LEVEL | OK | NG | LEAK | | | 14 POWER WINDOW (L FRONT) | OK | NG | | | NONE |
| 3 | ENGINE OIL LEVEL | OK | NG | DIRT | | | 15 POWER WINDOW (R REAR) | OK | NG | | | NONE |
| 4 | OIL LEAKING | OK | NG | SMALL | BIG | | 16 POWER WINDOW (L REAR) | OK | NG | | | NONE |
| 5 | TIRE (R FRONT) | OK | NG | 185/60R15 | | RFT | 17 A/C CONDITION | OK | NG | WIND BLOWS OK | CAN'T OPERATE | NONE |
| 6 | TIRE (L FRONT) | OK | NG | 185/60R15 | | RFT | 18 INTERIOR CONDITION | OK | NG | DIRT | SMOKING SMELL | OTHER SMELL |
| 7 | TIRE (R REAR) | OK | NG | 185/60R15 | | RFT | 19 CHECK / WARNING LAMP | OK | E/G | ABS | AIRBAG | OTHER |
| 8 | TIRE (L REAR) | OK | NG | 185/60R15 | | RFT | (COMMENT) | | | | TESTER CHECK | |
| 9 | ENGINE NOISE | OK | NG | E/G | OTHERS | | | | | | | |
| 10 | ENGINE CONDITION | OK | NG | IDLING | SMOKE | | | | | | | |
| 11 | EXHAUST LEAK | OK | NG | MUFFLER RUSTY | MISSING PARTS | | | | | | | |
| 12 | TRANSMISSION ((AT) / MT) | OK | NG | SHOCK | NOISE | SLIP | | | | | | |
| OPTION | | | | | | | | | | | | |
| RADIO | | C D | | | | | | | | | | |
| | | | | | | | | | | | | |
| (注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。 | | | | | | | | | | | | |
| (注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。 | | | | | | | | | | | | |

| | | | | | |
|------|----------------|-----------|----|----------|---|
| YARD | 名古屋(SPX上組 西五区) | INSPECTER | 小林 | AA SHEET | ✓ |
|------|----------------|-----------|----|----------|---|