

CONDITION CHECK REPORT

BF No.	BK317348	CHASSIS No.	H77W-5201651	DATE	2021 / 9 / 13
--------	----------	-------------	--------------	------	---------------

1	TIMING BELT CHANGE		<input checked="" type="radio"/> YES	96218	KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG			NONE
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	<input type="radio"/> NG	LEAK			14 POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG			NONE
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	<input type="radio"/> NG	DIRT			15 POWER WINDOW (R REAR)	<input checked="" type="radio"/> OK	NG			NONE
4	OIL LEAKING	<input checked="" type="radio"/> OK	<input type="radio"/> NG	SMALL	BIG		16 POWER WINDOW (L REAR)	<input checked="" type="radio"/> OK	NG			NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	<input type="radio"/> NG	215/70R16		RFT	17 A/C CONDITION	<input checked="" type="radio"/> OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	<input type="radio"/> NG	215/70R16		RFT	18 INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	<input type="radio"/> NG	215/70R16		RFT	19 CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	<input type="radio"/> NG	215/70R16		RFT	(COMMENT)				TESTER CHECK	
9	ENGINE NOISE	<input checked="" type="radio"/> OK	<input type="radio"/> NG	E/G	OTHERS							
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	<input type="radio"/> NG	IDLING	SMOKE							
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	<input type="radio"/> NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (<input checked="" type="radio"/> AT / <input type="radio"/> MT)	<input checked="" type="radio"/> OK	<input type="radio"/> NG	SHOCK	NOISE	SLIP						
OPTION												
<input checked="" type="radio"/> RADIO												
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD	神戸港島(GL 新日本トランス No.2)	INSPECTER	SIMON	AA SHEET	<input checked="" type="checkbox"/>
------	-----------------------	-----------	-------	----------	-------------------------------------