

CONDITION CHECK REPORT

A

BK No.	233 599	CHASSIS No.	U42T-0316513
--------	---------	-------------	--------------

DATE 2021/11/9 13:20

No.	Item	Status	Remarks	Remarks	Remarks	Remarks	Remarks	Remarks	Remarks	Remarks	Remarks	Remarks	Remarks	Remarks	Remarks	
1	TIMING BELT CHANGE		YES													NONE
2	COOLANT LEVEL	OK	NG	LEAK												NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT												NONE
4	OIL LEAKING	OK	NG	SMALL	BIG											NONE
5	TIRE (R FRONT)	OK	NG	145	R 12	RFT										NONE
6	TIRE (L FRONT)	OK	NG	/	R	RFT										NONE
7	TIRE (R REAR)	OK	NG	/	R	RFT										NONE
8	TIRE (L REAR)	OK	NG	/	R	RFT										NONE
9	ENGINE NOISE	OK	NG	E/G	OTHERS											NONE
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE											NONE
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS											NONE
12	TRANSMISSION (AT MT)	OK	NG	SHOCK	NOISE	SLIP										NONE
OPTION																
<input checked="" type="checkbox"/> RADIO		<input type="checkbox"/> C D		<input type="checkbox"/> DVD		<input type="checkbox"/> SUN ROOF		<input type="checkbox"/> FLIP DOWN MONITOR								
<input type="checkbox"/> REAR MONITOR		<input type="checkbox"/> BACK CAMERA		<input type="checkbox"/> CRUISE CONTROL		<input type="checkbox"/> POWER SLIDING DOOR (LEFT)		<input type="checkbox"/> POWER SLIDING DOOR (RIGHT)								
<input type="checkbox"/> POWER BACK DOOR																
(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「X」、オプション品が付いていないものは「無印」をお願いします。													(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。			

(COMMENT)

S-T (後輪 左側 ラジアルタイヤ)

シート汚れ大 工具欠

ステアリング欠

バッテリー X

ドアアッセンブリ欠

YARD KANALOA 新車

INSPECTER 宇庄

AA SHEET