

CONDITION CHECK REPORT

BF No.	BK337883	CHASSIS No.	S110P-027325	DATE	2021 / 9 / 22
--------	----------	-------------	--------------	------	---------------

1	TIMING BELT CHANGE		YES	100643	KM	13	POWER WINDOW (R FRONT)	OK	NG			NONE
2	COOLANT LEVEL	OK	NG	LEAK			POWER WINDOW (L FRONT)	OK	NG			NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT			POWER WINDOW (R REAR)	OK	NG			NONE
4	OIL LEAKING	OK	NG	SMALL	BIG		POWER WINDOW (L REAR)	OK	NG			NONE
5	TIRE (R FRONT)	OK	NG	145/ R12		RFT	A/C CONDITION	OK	NG	WIND BLOWS OK	CAN'T OPERATE	NONE
6	TIRE (L FRONT)	OK	NG	145/ R12		RFT	INTERIOR CONDITION	OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
7	TIRE (R REAR)	OK	NG	145/ R12		RFT	CHECK / WARNING LAMP	OK	E/G	ABS	AIRBAG	OTHER
8	TIRE (L REAR)	OK	NG	145/ R12		RFT	(COMMENT) NO A/C				TESTER CHECK	
9	ENGINE NOISE	OK	NG	E/G	OTHERS							
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE							
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	OK	NG	SHOCK	NOISE	SLIP						
OPTION												
	RADIO						(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。 オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカーで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。					

YARD	神戸(サンフェニックスRS-B)	INSPECTER	三浦	AA SHEET	✓
------	------------------	-----------	----	----------	---