

CONDITION CHECK REPORT

DATE 2021/11/13

BK No.	5/3927	CHASSIS No.	K13-316283
--------	--------	-------------	------------

No.	Item	Status		Tire		Tire Size	Tire Side	Tire Pressure	Other	Item	Status	Status	Status	Status
		OK	NG	SMALL	BIG									
1	TIMING BELT CHANGE		YES							13	POWER WINDOW (R FRONT)	OK	NG	NONE
2	COOLANT LEVEL	OK	NG	LEAK						14	POWER WINDOW (L FRONT)	OK	NG	NONE
3	ENGINE OIL LEVEL	OK	NG	DIRT						15	POWER WINDOW (R REAR)	OK	NG	NONE
4	OIL LEAKING	OK	NG	SMALL	BIG					16	POWER WINDOW (L REAR)	OK	NG	NONE
5	TIRE (R FRONT)	OK	NG	175/65 R14			RFT			17	A/C CONDITION	OK	NG	WIND BLOWS OK CAN'T OPERATE A/C NONE
6	TIRE (L FRONT)	OK	NG	/	R		RFT			18	INTERIOR CONDITION	OK	NG	DIRT SMOKING SMELL OTHER SMELL
7	TIRE (R REAR)	OK	NG	/	R		RFT			19	CHECK / WARNING LAMP	OK	E/G	ABS AIRBAG OTHER
8	TIRE (L REAR)	OK	NG	/	R		RFT		(COMMENT) 9 bus 24 if 3177 外ハット 2B					
9	ENGINE NOISE	OK	NG	E/G	OTHERS									
10	ENGINE CONDITION	OK	NG	IDLING	SMOKE									
11	EXHAUST LEAK	OK	NG	MUFFLER RUSTY	MISSING PARTS									
12	TRANSMISSION (AT/MT)	OK	NG	SHOCK	NOISE	SLIP								

TESTER CHECK

OPTION				
RADIO	CD	DVD	SUN ROOF	FLIP DOWN MONITOR
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)
POWER BACK DOOR				

(注意) オプション品が付いていて作動するものは「O」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。

(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3-B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。

YARD ECL 富津

INSPECTER [Signature]

AA SHEET 7