

CONDITION CHECK REPORT

BF No.	BK516791	CHASSIS No.	FB70BB-512678
--------	-----------------	-------------	----------------------

DATE 2021 / 11 / 17

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	(OK)	NG			NONE					
2	COOLANT LEVEL	(OK)	NG	LEAK			14 POWER WINDOW (L FRONT)	(OK)	NG			NONE					
3	ENGINE OIL LEVEL	(OK)	NG	DIRT			15 POWER WINDOW (R REAR)	OK	NG			NONE					
4	OIL LEAKING	OK	(NG)	(SMALL)	BIG		16 POWER WINDOW (L REAR)	OK	NG			NONE					
5	TIRE (R FRONT)	(OK)	NG	195 175-R 15	RFT		17 A/C CONDITION	(OK)	NG	WIND BLOWS OK	CAN'T OPERATE	A/C NONE					
6	TIRE (L FRONT)	(OK)	NG	195 175R 15	RFT		18 INTERIOR CONDITION	OK	(NG)	(DIRT)	SMOKING SMELL	OTHER SMELL					
7	TIRE (R REAR)	(OK)	NG	195 175 R 15	RFT		19 CHECK / WARNING LAMP	(OK)	E/G	ABS	AIRBAG	OTHER					
8	TIRE (L REAR)	(OK)	NG	195 175 R 15	RFT		(COMMENT) 。ジヤッキ欠 。カタハットカバーまわりホコリにじみ。車内全体汚れ 。CD不良(ディスク入らばい)のタワシ板のり跡。 。化オディオディスク汚れ不良。										
9	ENGINE NOISE	(OK)	NG	E/G	OTHERS												
10	ENGINE CONDITION	(OK)	NG	IDLING	SMOKE												
11	EXHAUST LEAK	(OK)	NG	MUFFLER RUSTY	MISSING PARTS												
12	TRANSMISSION (AT / MT)	(OK)	NG	SHOCK	NOISE	SLIP											
OPTION																	
(RADIO)	(C X)	DVD	SUN ROOF	FLIP DOWN MONITOR													
REAR MONITOR	BACK CAMERA	CRUISE CONTROL	POWER SLIDING DOOR (LEFT)	POWER SLIDING DOOR (RIGHT)													
POWER BACK DOOR																	
(注意) オプション品が付いていて作動するのは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」をお願いします。							(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(マーカで囲んで)、その他目立つ破損部分があった場合は、写真撮影をお願いします。										
YARD			ナガセ自動車株式会社				INSPECTER			栗岡			AA SHEET				